



July 2014

South Africa Inspections – General Information

This document provides information for those stakeholders requiring the mandatory vehicle pre-shipment Road Worthiness Inspection (RWI) for export to Uganda from South Africa Commencing the 1st November 2009.

South Africa inspection details are as follows;

BOOKINGS:

AFRICA VEHICLE INSPECTIONS (AVI)

121 Morewood Road

Clare Estate

Durban, South Africa 4001

Phone: +27-31-2693582

Fax: +27-31-2691298

E-mail: info@zavi.co.za

INSPECTION CRITERIA: The inspection is to assess the vehicle for;

- a. UNBS Roadworthiness Inspection.
- b. The vehicle should be free of CFC (R12) gas.
- c. No age limitation of the manufacturing year of vehicle.
- d. Left hand drive and Right hand drive are acceptable.

The vehicle must be presented with the original vehicle Registration Certificate.

INSPECTION ARRANGEMENT: All inspections will be undertaken at;

AFRICA VEHICLE INSPECTIONS (AVI)

121 Morewood Road

Clare Estate

Durban, South Africa 4001

Phone: +27-31-2693582

Fax: +27-31-2691298

E-mail: info@zavi.co.za

FEES: All inspection fees must be paid in the form of bank remittance, and the corresponding bank statement is to be submitted at the time of booking.

Inspection Fee: ZAR1685.00 + VAT

CERTIFICATE: JEVIC RWI Certificate will be dispatched COD once the vehicle successfully passes the inspection process.

Note: Any vehicle not inspected in South Africa and arriving in Uganda will incur a fee calculated on 15% CIF and subject to inspection upon arrival by UNBS.

Kind Regards

JEVIC Management